



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	297	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	6	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2122		Western Run	DR

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_A\A\_2004\_1018Image0023.JPG

**Image Status:** Image found and displayed.



**Photo No:** 24

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_A\A\_2004\_1018Image0024.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 297

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\297.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	297	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	6	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2120		Western Run	DR

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 25

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_A\A\_2004\_1018Image0025.JPG

**Image Status:** Image found and displayed.



**Photo No:** 26

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_A\A\_2004\_1018Image0026.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 297

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\297.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	297	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	6	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2130		Western Run	DR

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	4=Major
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0009.JPG

**Image Status:** Image found and displayed.



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0010.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 297

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\297.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	297	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	6	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2128		Western Run	DR

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0011.JPG

**Image Status:** Image found and displayed.



**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0012.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 297

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\297.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	297	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	6	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2126		Western Run	DR

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	200		

**Comments:** holes in ground

## SMOKE TEST PHOTOS



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0014.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 297

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\297.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	298	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	7	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 298

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\298.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

Unique Test ID	298	Date:	10/18/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	7	Priority CCTV:	

---

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

---

## SMOKE TEST PHOTOS

Photo No:  
Filename Path:  
  
Image Status: No image name specified.

Photo No:  
Filename Path:  
  
Image Status: No image name specified.

Photo No:  
Filename Path:  
  
Image Status: No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 298

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\298.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	299	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	8	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 299

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\299.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	299	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	8	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 299

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\299.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	300	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	9	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 300

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\300.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	300	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR01
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	9	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
2100		Western Run	DR		
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	4=Major
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		
<b>Comments:</b>	MH 0691198				

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 15

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0015.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 300

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\300.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	300	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WRR01
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	9	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2100		Western Run	DR

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	4=Major
---------------------	-------------------	------------------	----------	------------------	---------

<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0
----------------	----------	-----------------------	---

**Comments:** MH 0691200

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 16

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-1\PLAYER\_B\B\_2004\_1018Image0016.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 300

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\300.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

Unique Test ID	301	Date:	10/18/2004	MeterBasin:	
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	10	Priority CCTV:	

**House Number    Street Prefix:    Street Name:    Street Type:**

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

## SMOKE TEST PHOTOS

**Photo No:****Filename Path:**

**Image Status:** No image name specified.

**Photo No:****Filename Path:**

**Image Status:** No image name specified.

**Photo No:****Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 301

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\301.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	301	Date:	10/18/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	10	Priority CCTV:	

---

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

## SMOKE TEST PHOTOS

Photo No:  
Filename Path:  
Image Status: No image name specified.

Photo No:  
Filename Path:  
Image Status: No image name specified.


Photo No:  
Filename Path:  
Image Status: No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 301

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\301.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	302	<b>Date:</b>	10/25/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Kelly	AVE

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	4=Major
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		

**Comments:** MH 00691313- See field sketch

## SMOKE TEST PHOTOS



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 302

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\302.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	302	<b>Date:</b>	10/25/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Kelly	AVE

<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	30		

**Comments:** beside MH 00691313- See field sketch

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0002.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 302

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\302.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	302	<b>Date:</b>	10/25/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Kelly	AVE

<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	150		

**Comments:** beside MH 00691313- See field sketch

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0002.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 302

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\302.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	302	<b>Date:</b>	10/25/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Kelly	AVE

<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	11=Field	<b>Severity:</b>	4=Major
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	1000		

**Comments:** 25 ft. west of MH 00691313- See field sketch

## SMOKE TEST PHOTOS



**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0004.JPG

**Image Status:** Image found and displayed.



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_A\A\_2004\_1025Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 302

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\302.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	302	<b>Date:</b>	10/25/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2200		Kelly	AVE

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	4=Major
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		

**Comments:** MH 00691171- See field sketch

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_B\B\_2004\_1025Image0001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_B\B\_2004\_1025Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 302

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\302.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	302	<b>Date:</b>	10/25/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
2200		Kelly	AVE		
<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	1000		
<b>Comments:</b>	MH 00691170- See field sketch				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1025-2004\T-1\PLAYER\_B\B\_2004\_1025Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 302

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\302.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*